


GENESEE RIVER

— FLOW →



**GENESEE YACHT CLUB**

ROCHESTER, NEW YORK

**Dock Piling Clearances**

**November 4, 2014**

SCALE ~24 FEET = 1 INCH

DRAWN BY: T.W.ALLEN

DATE DRAWN 24 JULY 1987  
REVISED: 11/5/14 s.corona

Measurements at docks 17 and 21 are minimum clearance due to leaning piles.

Lake Level at ft. (NOAA)

Measurements taken by  
Bibbens, Cecchi, Corona, Rodgers





